








# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Cencal Builders	<b>Type of Inspection:</b>	Boom Lift
<b>Project</b>	Copper River Apt	<b>Date of Inspection</b>	July 15, 2021
<b>Inspector Name</b>	jesus.cencalbuilders@gmail.com	<b>Time of Inspection</b>	08:12 AM

## INSPECTION ITEMS

Item	Comment	Photo
Click "Satisfactory" and enter the boom lift model # in the comments below	Satisfactory	-
Is the lift in overall good condition and the platform clean?	Satisfactory	
Are there full body harnesses available with the correct lanyard for those working in the basket?	Satisfactory	
Are the indicator lights working?	Satisfactory	
Perform a platform control check. Does everything operate smoothly?	Satisfactory	
Perform a ground control check. Does everything operate smoothly?	Satisfactory	-
Are the tires in safe condition?	Satisfactory	
Are the platform anchor point(s) in place and clearly labeled?	Satisfactory	-

Are the guardrails and platform door in securely in place?	Satisfactory		-
Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?	Satisfactory		-
Is the owners manual in place?	Satisfactory		-
Are the structure, pins and covers in good condition?	Satisfactory		-
Does the horn work?	Satisfactory		-
Is the moving alarm working?	Satisfactory		-