



# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

|                       |                  |                            |                   |
|-----------------------|------------------|----------------------------|-------------------|
| <b>Company</b>        | Cencal Builders  | <b>Type of Inspection:</b> | Fork Lift         |
| <b>Project</b>        | Copper River Apt | <b>Date of Inspection</b>  | December 10, 2021 |
| <b>Inspector Name</b> | Shawn Garcia     | <b>Time of Inspection</b>  | 08:22 AM          |

## INSPECTION ITEMS

| Item   | Comment        | Photo |
|--|----------------|-------|
| Click "Satisfactory" and enter the fork lift model # in the comments below   | Satisfactory   | -     |
| Is the owners manual in place?   | Satisfactory   | -     |
| Is the seat belt in place and in safe condition?   | Satisfactory   | -     |
| Is the lift's weight capacity legible?   | Satisfactory   | -     |
| Is the manufacturer name plate in place and legible?   | Satisfactory   | -     |
| Do the fork controls operate smoothly and safely?  | Satisfactory   | -     |
| Do the lift's brakes work?   | Satisfactory   | -     |
| Does the emergency brake work?   | Satisfactory   | -     |
| If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions? | Satisfactory   | -     |
| Is the mast securely in place?   | Satisfactory   | -     |
| Are the fluid levels good? (oil, fuel, water, etc)   | Satisfactory   | -     |
| Is the lift free of leaks?   | Unsatisfactory | -     |
| Are hoses and chains in safe condition?  | Satisfactory   | -     |
| Does the horn work?  | Satisfactory   | -     |
| Are the headlights and brake lights in good working order?   | Satisfactory   | -     |
| Is the overheard guard securely in place and in safe condition?  | Satisfactory   | -     |
| Are the forks in safe condition?   | Satisfactory   | -     |

|  |              |  |   |
|--|--------------|--|---|
| Are the tires in safe condition?       | Satisfactory |  | - |
| Is the lift in overall good condition? | Satisfactory |  | - |

## UNSATISFACTORY ITEMS

| Photo | Comment                                    | Corrective Action |
|-------|--|-------------------|
| -     | The joystick and both front drums leak ... |                   |