



# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)


<b>Company</b>	Cencal Builders	<b>Type of Inspection:</b>	Fork Lift
<b>Project</b>	Copper River Apt	<b>Date of Inspection</b>	March 07, 2022
<b>Inspector Name</b>	Shawn Garcia	<b>Time of Inspection</b>	07:18 AM

## INSPECTION ITEMS

Item	Comment	Photo
Click "Satisfactory" and enter the fork lift model # in the comments below	Satisfactory	-
Is the owners manual in place?	Satisfactory	-
Is the seat belt in place and in safe condition?	Satisfactory	-
Is the lift's weight capacity legible?	Satisfactory	-
Is the manufacturer name plate in place and legible?	Satisfactory	-
Do the fork controls operate smoothly and safely?	Satisfactory	-
Do the lift's brakes work?	Satisfactory	-
Does the emergency brake work?	Satisfactory	-
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?	Satisfactory	-
Is the mast securely in place?	Satisfactory	-
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory	-
Is the lift free of leaks?	Unsatisfactory	-
Are hoses and chains in safe condition?	Satisfactory	-
Does the horn work?	Satisfactory	-
Are the headlights and brake lights in good working order?	Satisfactory	-
Is the overhead guard securely in place and in safe condition?	Satisfactory	-
Are the forks in safe condition?	Satisfactory	-

Are the tires in safe condition?	Satisfactory		-
Is the lift in overall good condition?	Satisfactory		-

## UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
	<p>Boom and the front right inside rim ...</p>	