



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com


Company	Cencal Builders	Type of Inspection:	Fork Lift
Project	Copper River Apt	Date of Inspection	May 16, 2022
Inspector Name	Shawn Garcia	Time of Inspection	11:18 AM

INSPECTION ITEMS

Item		Comment	Photo
Click "Satisfactory" and enter the fork lift model # in the comments below	Satisfactory	Different Forklift K10 882008RA	-
Is the owners manual in place?	Satisfactory		-
Is the seat belt in place and in safe condition?	Satisfactory		-
Is the lift's weight capacity legible?	Satisfactory		-
Is the manufacturer name plate in place and legible?	Satisfactory		-
Do the fork controls operate smoothly and safely?	Satisfactory		-
Do the lift's brakes work?	Unsatisfactory		-
Does the emergency brake work?	Satisfactory		-
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?	Satisfactory		-
Is the mast securely in place?	Satisfactory		-
Are the fluid levels good? (oil, fuel, water, etc)	Unsatisfactory		-
Is the lift free of leaks?	Unsatisfactory		-
Are hoses and chains in safe condition?	Satisfactory		-
Does the horn work?	Satisfactory		-
Are the headlights and brake lights in good working order?	Satisfactory		-
Is the overheard guard securely in place and in safe condition?	Unsatisfactory		-
Are the forks in safe condition?	Satisfactory		-

Are the tires in safe condition?	Unsatisfactory		-
Is the lift in overall good condition?	Unsatisfactory		-

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
-	There's a problem with brakes (Don't feel right)	
-	Had to put oil ...	
-	Leaks	
	There's a crack in window ...	
-	Garbage	
-		