




# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Cencal Builders	<b>Type of Inspection:</b>	Framing Inspection
<b>Project</b>	Veneto (Spruce/ Peach)	<b>Date of Inspection</b>	August 17, 2021
<b>Inspector Name</b>	veronica@cencal-builders.com	<b>Time of Inspection</b>	12:08 PM

## INSPECTION ITEMS

Item		Comment	Photo
Are air compressors and generators set up safely?	Satisfactory		-
Are nail guns being used safely?	Satisfactory		-
Are hole and wall openings protected per OSHA regulations?	Satisfactory		-
Are stairways in place as required?	N/A		-
If personal fall restraint / arrest systems are being used, are the anchors and lanyards set up correctly?	Satisfactory		-
is emergency equipment, including first aid kits and fire extinguishers available?	Satisfactory		-
Are emergency and labor law postings in place?	Satisfactory		-
Is scaffolding set up correctly and being used safely?	N/A		-
Is fall protection in place where required?	Satisfactory		-
Is all required PPE being worn including hard hats and eye protection?	Satisfactory		-
Are electrical cords and other electrical related items in safe condition?	Satisfactory		-
Are hand and power tools being used safely?	Satisfactory		-
Is the company safety manual on site?	Satisfactory		
Are SDS on site and available to employees?	Satisfactory		-