




PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Cencal Builders	Type of Inspection:	Framing Inspection
Project	Veneto (Spruce/ Peach)	Date of Inspection	August 19, 2021
Inspector Name	veronica@cencal-builders.com	Time of Inspection	10:01 AM

INSPECTION ITEMS

Item	Comment	Photo
Are air compressors and generators set up safely?	Satisfactory	-
Are nail guns being used safely?	Satisfactory	-
Are hole and wall openings protected per OSHA regulations?	Satisfactory	-
Are stairways in place as required?	N/A	-
If personal fall restraint / arrest systems are being used, are the anchors and lanyards set up correctly?	N/A	-
is emergency equipment, including first aid kits and fire extinguishers available?	Satisfactory	-
Are emergency and labor law postings in place?	Satisfactory	-
Is scaffolding set up correctly and being used safely?	N/A	-
Is fall protection in place where required?	Satisfactory	-
Is all required PPE being worn including hard hats and eye protection?	Satisfactory	-
Are electrical cords and other electrical related items in safe condition?	Satisfactory	-
Are hand and power tools being used safely?	Satisfactory	-
Is the company safety manual on site?	Satisfactory	
Are SDS on site and available to employees?	Satisfactory	-