

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Cencal Builders	Type of Inspection:	Framing Inspection
Dreiget	Veneta (Caruca / Deceh)	Date of	February 19, 2022
Project	Veneto (Spruce/ Peach)	Inspection	February 18, 2022
Inspector Name	Samuel Perez	Time of Inspection	08:39 AM

INSPECTION ITEMS

Item		Comment	Photo
Are air compressors and generators set up safely?	Satisfactory		-
Are nail guns being used safely?	Satisfactory		-
Are hole and wall openings protected per OSHA regulations?	Satisfactory		-
Are stairways in place as required?	Satisfactory		-
If personal fall restraint / arrest systems are being used, are the anchors and lanyards set up correctly?	Satisfactory		-
is emergency equipment, including first aid kits and fire extinguishers available?	Satisfactory		-
Are emergency and labor law postings in place?	Satisfactory		-
Is scaffolding set up correctly and being used safely?	N/A		-
Is fall protection in place where required?	Satisfactory		-
Is all required PPE being worn including hard hats and eye protection?	Satisfactory		-
Are electrical cords and other electrical related items in safe condition?	Satisfactory		-
Are hand and power tools being used safely?	Satisfactory		-
Is the company safety manual on site?	Satisfactory		-
Are SDS on site and available to employees?	Satisfactory		-