



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Cencal Builders	<b>Type of Inspection:</b>	Cencal Framing Inspection
<b>Project</b>	Veneto (Spruce/ Peach)	<b>Date of Inspection</b>	February 23, 2022
<b>Inspector Name</b>	Samuel Perez	<b>Time of Inspection</b>	09:37 AM

## INSPECTION ITEMS

Item	Comment	Photo
Are air compressors and generators set up safely?	Satisfactory	-
Are nail guns being used safely?	Satisfactory	-
Are hole and wall openings protected per OSHA regulations?	Satisfactory	-
Are stairways in place as required?	Satisfactory	-
If personal fall restraint / arrest systems are being used, are the anchors and lanyards set up correctly?	Satisfactory	-
is emergency equipment, including first aid kits and fire extinguishers available?	Satisfactory	-
Are emergency and labor law postings in place?	Satisfactory	-
Is scaffolding set up correctly and being used safely?	N/A	-
Is fall protection in place where required?	Satisfactory	-
Is all required PPE being worn including hard hats and eye protection?	Satisfactory	-
Are electrical cords and other electrical related items in safe condition?	Satisfactory	-
Are hand and power tools being used safely?	Satisfactory	-
Is the company safety manual on site?	Satisfactory	-
Are SDS on site and available to employees?	Satisfactory	-
Are ladders in safe condition, being used safely, and have the manufacturer labeling in place and legible?	Satisfactory	-

Are roofing operations being performed safely?	Satisfactory		-
Is demolition work being done safely?	Satisfactory		-
Are all other tasks being performed safely?	Satisfactory		-
Are ladders in safe condition, being used safely, and have the manufacturer labeling in place and legible?	Satisfactory		-