

## **EQUIPMENT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Power Truck - Reach Lift
Project	19-003	Date of Inspection	November 12, 2019
Inspector Name	Rwhite	Time of Inspection	10:23 AM

## **INSPECTION ITEMS**

Item		Comment	Photo
Click "Satisfactory" and enter the reach lift model # in the comments below	Satisfactory	Sky track JLG 10042	-
Is the owners manual in place?	Satisfactory	Yes	
Is any rigging being used tagged, rated for the loads being handled, and rigged by a qualified rigger?	Satisfactory	No rigging	-
Does the emergency brake work?	Satisfactory	Yes	-
Do the lift's brakes work?	Satisfactory	Yes	-
Do the fork controls operate smoothly and safely?	Satisfactory	Yes	-
is the manufacturer name plate in place and legible?	Satisfactory	Yes	-
Is the load chart in place?	Satisfactory	Yes	10042
Is the lift's level working properly?	Satisfactory	Yes	-
Does the horn work?	Satisfactory	Yes	-

Do all machine / fork controls operate smoothly?	Satisfactory	Yes	-
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturers instructions?	N/A		-
Is the mast securely in place?	Satisfactory	Yes	-
Is the lift in overall good condition?	Satisfactory	It runs and works	-
Are the tires in safe condition?	Satisfactory	3 out of 4 are good one looks a little low but there Foam filled tires	-
Are the forks in safe condition?	Satisfactory	Yes	-
Is the operators cab securely in place and in safe condition?	Satisfactory	Yes	-
Are the headlights and brake lights in good working order?	N/A		-
Does the horn work?	Satisfactory	Yes	-
Are hoses and chains in safe condition?	Satisfactory	Yes	-
Is the lift free of leaks?	Unsatisfactory	No	-
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory	Yes	-

## **UNSATISFACTORY ITEMS**

Photo Comment Corrective Action

The lift is leaking from around the steering wheel

I will call are Mechanic to come look at it