




EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Fork Lift
Project	19-003	Date of Inspection	November 18, 2019
Inspector Name	Rwhite	Time of Inspection	08:44 AM

INSPECTION ITEMS

Item		Comment	Photo
Click "Satisfactory" and enter the fork lift model # in the comments below	Satisfactory	JLG 1255	-
Is the owners manual in place?	Satisfactory	Yes	-
Is the seat belt in place and in safe condition?	Satisfactory	Yes	-
Is the lift's weight capacity legible?	Satisfactory	Yes	-
Is the manufacturer name plate in place and legible?	Satisfactory	Yes	-
Do the fork controls operate smoothly and safely?	Satisfactory	Yes	-
Do the lift's brakes work?	Satisfactory	Yes	-
Does the emergency brake work?	Satisfactory	Yes	-
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?	Satisfactory	Is being used and yes	
Is the mast securely in place?	Satisfactory	Boom lift	-
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory	Yes	-
Is the lift free of leaks?	Satisfactory	Yes	-
Are hoses and chains in safe condition?	Satisfactory	Yes	-
Does the horn work?	Satisfactory	Yes	-
Are the headlights and brake lights in good working order?	Satisfactory	Yes	-

Is the overhead guard securely in place and in safe condition?	Satisfactory	Yes	-
Are the forks in safe condition?	Satisfactory	Yes	-
Are the tires in safe condition?	Satisfactory	Yes	
Is the lift in overall good condition?	Satisfactory	Like new	