

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Skid Steer
Project	19-003	Date of Inspection	November 22, 2019
Inspector Name	Rwhite	Time of Inspection	08:26 AM

INSPECTION ITEMS

ltem		Comment	Photo
Click "Satisfactory" and enter the skid steer model # in the comments below	Satisfactory	Bobcat T650	-
Hour meter reading available? (Enter reading in comments below)	Satisfactory	316.9	-
Is the ignition and electrical system working correctly? Are all gauges and instruments visible and working correctly?	Satisfactory	Yes	-
Are the warning lights (and lights, if applicable) working correctly?	Satisfactory	All are working	-
Are the brakes working correctly?	Satisfactory	Parking brake works	-
Is the moving alarm audible and working correctly?	Satisfactory	Yes	-
Does the engine sound normal?	Satisfactory	Sounds good	-
Do the steering controls all work normally, including response time?	Satisfactory	Everything is working smoothly	-
Is the instrumentation operating normally and legible?	Satisfactory	Yes	-
Do the levers (switches, toggles, joysticks, sticks, etc) work smoothly and safely?	Satisfactory	Yes	-
Is the exhaust in a safe condition with no excessive smoke, sparks or flames?	Satisfactory	ls good	-
Are the safety decks / warning stickers visible and legible?	Satisfactory	Yes	-
Is the operators manual in place?	Satisfactory	Yes	-
Is the air filter free of dust and trash build up?	Satisfactory	lt's clean	-
Is the chassis free of structural damage? Is the turntable lubricated?	Satisfactory	No damage but could be greased	-

Is the bucket and teeth in safe condition free of structural damage and/or wear?	Satisfactory	Bucket is good	-
Is the coolant system free of leaks and damage? is the coolant level good?	Satisfactory	No leaks and not overheating	-
Is the engine oil level good? Are there any leaks?	Satisfactory	Oil level is good. Last changed at 248 hours	-
Are the engine belts free of wear and damage?	Satisfactory	Belts look good	-
Is the fuel system in good condition, including the fuel level?	Satisfactory	No leaks and is full	
Is the hydraulic system in good condition? Are the hydraulic level and filters good?	Satisfactory	Level is good no leaks	-
Are the tracks / wheels in good condition and free of wear and damage?	Satisfactory	Tracks are good	-
Is the operator cab clean, items secure, and free of damage?	Satisfactory	Could clean under the foot peddles	-
Other items?	Satisfactory	All is well	-