







EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Fork Lift
Project	19-003	Date of Inspection	December 03, 2019
Inspector Name	Rwhite	Time of Inspection	08:02 AM

INSPECTION ITEMS

Item		Comment	Photo
Click "Satisfactory" and enter the fork lift model # in the comments below	Satisfactory	JCB 510-56	-
Is the owners manual in place?	Satisfactory	Yes	-
Is the seat belt in place and in safe condition?	Satisfactory	Yes	-
Is the lift's weight capacity legible?	Satisfactory	Yes	
Is the manufacturer name plate in place and legible?	Satisfactory	Yes	
Do the fork controls operate smoothly and safely?	Satisfactory	Yes	-
Do the lift's brakes work?	Satisfactory	Yes	-
Does the emergency brake work?	Satisfactory	Yes	-

<p>If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturer's instructions?</p>	<p>Satisfactory</p>	<p>Yes</p>	
<p>Is the mast securely in place?</p>	<p>Satisfactory</p>	<p>Boom lift</p>	<p>-</p>
<p>Are the fluid levels good? (oil, fuel, water, etc)</p>	<p>Satisfactory</p>	<p>Yes</p>	<p>-</p>
<p>Is the lift free of leaks?</p>	<p>Satisfactory</p>	<p>Yes</p>	<p>-</p>
<p>Are hoses and chains in safe condition?</p>	<p>Satisfactory</p>	<p>Yes</p>	<p>-</p>
<p>Does the horn work?</p>	<p>Satisfactory</p>	<p>Yes</p>	<p>-</p>
<p>Are the headlights and brake lights in good working order?</p>	<p>Satisfactory</p>	<p>Yes</p>	
<p>Is the overhead guard securely in place and in safe condition?</p>	<p>Satisfactory</p>	<p>Yes</p>	<p>-</p>
<p>Are the forks in safe condition?</p>	<p>Satisfactory</p>	<p>Yes</p>	<p>-</p>
<p>Are the tires in safe condition?</p>	<p>Satisfactory</p>	<p>Yes</p>	<p>-</p>
<p>Is the lift in overall good condition?</p>	<p>Satisfactory</p>	<p>Yes</p>	<p>-</p>