




EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Boom Lift
Project	19-003	Date of Inspection	July 08, 2020
Inspector Name	Woody Petkovich	Time of Inspection	06:35 AM

INSPECTION ITEMS

Item	Comment	Photo
Click "Satisfactory" and enter the boom lift model # in the comments below	Satisfactory	
Is the lift in overall good condition and the platform clean?	Satisfactory	-
Are there full body harnesses available with the correct lanyard for those working in the basket?	Satisfactory	-
Are the indicator lights working?	Satisfactory	-
Perform a platform control check. Does everything operate smoothly?	Satisfactory	-
Perform a ground control check. Does everything operate smoothly?	Satisfactory	-
Are the tires in safe condition?	Satisfactory	-
Are the platform anchor point(s) in place and clearly labeled?	Satisfactory	-
Are the guardrails and platform door in securely in place?	Satisfactory	-
Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?	Satisfactory	-
Is the owners manual in place?	Satisfactory	-
Are the structure, pins and covers in good condition?	Satisfactory	-
Does the horn work?	Satisfactory	-
Are the tires in good condition?	Satisfactory	-
Is the moving alarm working?	Satisfactory	-