



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| | | | |
|-----------------------|----------------------------|----------------------------|------------------------------------|
| Company | Concrete North, Inc. | Type of Inspection: | Concrete North COVID-19 Inspection |
| Project | 20-014 Arden Middle School | Date of Inspection | September 21, 2020 |
| Inspector Name | Eddy Navarro | Time of Inspection | 06:30 AM |

INSPECTION ITEMS

| Item | | Comment | Photo |
|---|--------------|---------|-------|
| Click "Satisfactory" and enter the general contractor in the comments section below. | Satisfactory | | - |
| Click "Satisfactory" and enter the general contractor COVID-19 contact in the comments section below. | Satisfactory | | - |
| Are sanitization stations available? | Satisfactory | | - |
| Are temperature checks being done regularly? | Satisfactory | | - |
| Are common areas being sanitized? | Satisfactory | | - |
| Were COVID-19 supplies provided? | Satisfactory | | - |
| Was COVID-19 training provided to all employees? | Satisfactory | | - |