



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Concrete North, Inc.	<b>Type of Inspection:</b>	Concrete North COVID-19 Inspection
<b>Project</b>	20-014 Arden Middle School	<b>Date of Inspection</b>	November 11, 2020
<b>Inspector Name</b>	Eddy Navarro	<b>Time of Inspection</b>	06:30 AM

## INSPECTION ITEMS

Item		Comment	Photo
Click "Satisfactory" and enter the general contractor in the comments section below.	Satisfactory		-
Click "Satisfactory" and enter the general contractor COVID-19 contact in the comments section below.	Satisfactory		-
Are sanitization stations available?	Satisfactory		-
Are temperature checks being done regularly?	Satisfactory		-
Are common areas being sanitized?	Satisfactory		-
Were COVID-19 supplies provided?	Satisfactory		-
Was COVID-19 training provided to all employees?	Satisfactory		-
Is good housekeeping being maintained?	Satisfactory		-
Is fall protection in place where required?	N/A		-
Is trenching & excavation work being done safely?	N/A		-
Are confined space safety procedures being followed?	N/A		-
Are scissor lifts / elevated platforms being used safely?	N/A		-
Are boom lifts and other aerial devices being used safely?	N/A		-
Is heavy equipment being used safely?	N/A		-
Are electrical items being used safely?	Satisfactory		-
Are roofing operations being performed safely?	N/A		-

Is demolition work being done safely?	N/A		-
Are all other tasks being performed safely?	Satisfactory		-