



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Concrete North, Inc.	<b>Type of Inspection:</b>	CNI COVID-19 Sanitization (3X DAILY)
<b>Project</b>	21-017 fremont amtrak	<b>Date of Inspection</b>	July 20, 2022
<b>Inspector Name</b>	Tony Ramos	<b>Time of Inspection</b>	10:16 AM

## INSPECTION ITEMS

Item		Comment	Photo
All hand tools have been sanitized.	Satisfactory		-
All power tools have been sanitized.	Satisfactory		-
All equipment has been sanitized.	Satisfactory		-
All common areas have been sanitized.	Satisfactory		-
Is Personal Protective Equipment being worn as required?	Satisfactory		-
Are scaffolding safety procedures being followed?	N/A		-
Are hand and power tools being used safely?	Satisfactory		-
Is good housekeeping being maintained?	Satisfactory		-
Is fall protection in place where required?	N/A		-
Is trenching & excavation work being done safely?	N/A		-
Are confined space safety procedures being followed?	N/A		-
Are scissor lifts / elevated platforms being used safely?	N/A		-
Are boom lifts and other aerial devices being used safely?	N/A		-
Is heavy equipment being used safely?	N/A		-
Are electrical items being used safely?	Satisfactory		-
Are roofing operations being performed safely?	N/A		-
Is demolition work being done safely?	N/A		-

Are all other tasks being performed safely?	Satisfactory		-
---	--------------	--	---