






PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	General Construction
Project	21-017 fremont amtrak	Date of Inspection	April 28, 2023
Inspector Name	Tony Ramos	Time of Inspection	09:14 AM

INSPECTION ITEMS

Item	Comment	Photo
Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory	
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory	-
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory	
Are emergency and labor law postings in place?	Satisfactory	
Is Personal Protective Equipment being worn as required?	Satisfactory	-
Are scaffolding safety procedures being followed?	N/A	-

Are hand and power tools being used safely?	Satisfactory		-
Is good housekeeping being maintained?	Satisfactory		-
Is fall protection in place where required?	N/A		-
Is trenching & excavation work being done safely?	N/A		-
Are confined space safety procedures being followed?	N/A		-
Are scissor lifts / elevated platforms being used safely?	N/A		-
Are boom lifts and other aerial devices being used safely?	N/A		-
Is heavy equipment being used safely?	N/A		-
Are electrical items being used safely?	Satisfactory		-
Are roofing operations being performed safely?	N/A		-
Is demolition work being done safely?	N/A		-
Are all other tasks being performed safely?	Satisfactory		-