



# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

|                       |                       |                            |                      |
|-----------------------|-----------------------|----------------------------|----------------------|
| <b>Company</b>        | Concrete North, Inc.  | <b>Type of Inspection:</b> | General Construction |
| <b>Project</b>        | 21-017 fremont amtrak | <b>Date of Inspection</b>  | May 02, 2023         |
| <b>Inspector Name</b> | Tony Ramos            | <b>Time of Inspection</b>  | 08:12 AM             |

## INSPECTION ITEMS

| Item                                                                                   |              | Comment | Photo |
|----------------------------------------------------------------------------------------|--------------|---------|-------|
| Is emergency equipment available, including first aid kit(s) and fire extinguisher(s)? | Satisfactory |         | -     |
| Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)    | Satisfactory |         | -     |
| Is drinking water and shade set up sufficient for the amount of workers?               | Satisfactory |         | -     |
| Are emergency and labor law postings in place?                                         | Satisfactory |         | -     |
| Is Personal Protective Equipment being worn as required?                               | Satisfactory |         | -     |
| Are scaffolding safety procedures being followed?                                      | N/A          |         | -     |
| Are hand and power tools being used safely?                                            | Satisfactory |         | -     |
| Is good housekeeping being maintained?                                                 | Satisfactory |         | -     |
| Is fall protection in place where required?                                            | N/A          |         | -     |
| Is trenching & excavation work being done safely?                                      | N/A          |         | -     |
| Are confined space safety procedures being followed?                                   | N/A          |         | -     |
| Are scissor lifts / elevated platforms being used safely?                              | N/A          |         | -     |
| Are boom lifts and other aerial devices being used safely?                             | N/A          |         | -     |
| Is heavy equipment being used safely?                                                  | N/A          |         | -     |
| Are electrical items being used safely?                                                | Satisfactory |         | -     |

|                                                |              |  |   |
|------------------------------------------------|--------------|--|---|
| Are roofing operations being performed safely? | N/A          |  | - |
| Is demolition work being done safely?          | N/A          |  | - |
| Are all other tasks being performed safely?    | Satisfactory |  | - |