



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Georgia Buggy
Project	21-052 Earl Crabb HS	Date of Inspection	January 12, 2023
Inspector Name	Eduardo	Time of Inspection	08:11 AM

INSPECTION ITEMS

Item	Comment	Photo
Oil levels are good	Satisfactory	-
Fuel level is good	Satisfactory	-
Tires have good tread	Satisfactory	-
Hydraulics are not leaking and are working properly	Satisfactory	-
Breaks on the buggy are in good and working condition	Satisfactory	-
Bucket is in good shape	Satisfactory	-
No leaks or drips	Satisfactory	-