



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Georgia Buggy
Project	22-030 caroline wenzel Elementary school	Date of Inspection	September 27, 2022
Inspector Name	Eduardo	Time of Inspection	06:01 AM

INSPECTION ITEMS

Item		Comment	Photo
Oil levels are good	Satisfactory		-
Fuel level is good	Satisfactory		-
Tires have good tread	Satisfactory		-
Hydraulics are not leaking and are working properly	Satisfactory		-
Breaks on the buggy are in good and working condition	Satisfactory		-
Bucket is in good shape	Satisfactory		-
No leaks or drips	Satisfactory		-