











PROJECT INSPECTION


Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	General Construction
Project	22-032	Date of Inspection	August 31, 2022
Inspector Name	JFriday	Time of Inspection	07:54 AM

INSPECTION ITEMS

Item		Comment	Photo
is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory	In CNI headache shack	
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory	Yes in foreman tablets	-
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory	Yes	
Are emergency and labor law postings in place?	Satisfactory	At turner office	
Is Personal Protective Equipment being worn as required?	Satisfactory	Yes	

Are scaffolding safety procedures being followed?	N/A		-
Are hand and power tools being used safely?	Satisfactory	All cuts on elevated platform	
Is good housekeeping being maintained?	Satisfactory	Yes all material is stacked and organized	
Is fall protection in place where required?	N/A		-
Is trenching & excavation work being done safely?	Satisfactory	Yes	
Are confined space safety procedures being followed?	N/A		-
Are scissor lifts / elevated platforms being used safely?	N/A		-
Are boom lifts and other aerial devices being used safely?	N/A		-
Is heavy equipment being used safely?	Satisfactory		

<p>Are electrical items being used safely?</p>	<p>Satisfactory</p>	<p>Batteries being out of sun and charged</p>	
<p>Are roofing operations being performed safely?</p>	<p>N/A</p>		<p>-</p>
<p>Is demolition work being done safely?</p>	<p>N/A</p>		<p>-</p>
<p>Are all other tasks being performed safely?</p>	<p>Satisfactory</p>	<p>Laser below eye level</p>	