



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Concrete North, Inc.	Type of Inspection:	Power Truck - Reach Lift
Project	23-021 CAM 1 Redwood	Date of Inspection	October 05, 2023
Inspector Name	Richard Smith	Time of Inspection	06:12 AM

INSPECTION ITEMS

Item		Comment	Photo
Click "Satisfactory" and enter the reach lift model # in the comments below	Satisfactory	JLG 100-54	-
Is the owners manual in place?	Satisfactory		-
Is any rigging being used tagged, rated for the loads being handled, and rigged by a qualified rigger?	N/A		-
Does the emergency brake work?	Satisfactory		-
Do the lift's brakes work?	Satisfactory		-
Do the fork controls operate smoothly and safely?	Satisfactory		-
is the manufacturer name plate in place and legible?	Satisfactory		-
Is the load chart in place?	Satisfactory		-
Is the lift's level working properly?	Satisfactory		-
Does the horn work?	Satisfactory		-
Do all machine / fork controls operate smoothly?	Satisfactory		-
If extensions are being used, are they rated for use, in safe condition, and attached per the manufacturers instructions?	N/A		-
Is the mast securely in place?	Satisfactory		-
Is the lift in overall good condition?	Satisfactory		-
Are the tires in safe condition?	Satisfactory		-
Are the forks in safe condition?	Satisfactory		-
Is the operators cab securely in place and in safe condition?	Satisfactory		-

Are the headlights and brake lights in good working order?	Satisfactory		-
Does the horn work?	Satisfactory		-
Are hoses and chains in safe condition?	Satisfactory		-
Is the lift free of leaks?	Satisfactory		-
Are the fluid levels good? (oil, fuel, water, etc)	Satisfactory		-