

PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| Company | Helio | Type of Inspection: | SCC USE ONLY: General Contractor Review |
|----------------|---------------|-----------------------|---|
| Project | Arya | Date of Inspection | October 10, 2022 |
| Inspector Name | Jeremy Chavez | Time of Inspection | 09:00 AM |

INSPECTION ITEMS

| Item | | Comment | Photo | |
|----------------------------|--------------|--|-------|--|
| Safety Manual | Satisfactory | | - | |
| Tailgate Meetings | N/A | The superintendent will confirm the status of tailgate meetings. | - | |
| SDS | Satisfactory | | - | |
| Daily Inspection | Satisfactory | The superintendent has documented today's safety inspection. Excellent job. | | |
| Sub-Contractor Meetings | N/A | | - | |
| Labor Law Posters | Satisfactory | Labor Laws are posted, however the Operating Rules for Industrial Trucks and the Code of Safe Practices are still pending. | - | |
| Codes/Emergency Posters | Satisfactory | | - | |
| Permits | Satisfactory | | - | |
| Fire Extinguisher | Satisfactory | | - | |
| Building Fire Extinguisher | Satisfactory | Fire extinguishers are located throughout the project. | | |
| First Aid Kit | Satisfactory | | - | |
| First Aid/CPR Cert | Satisfactory | | - | |
| Restrooms/Wash Stations | Satisfactory | | - | |
| Waste Containers | Satisfactory | | - | |
| Water Supply | Satisfactory | | - | |
| | | | | |

| Shade | Satisfactory | | - |
|-------------------------------|----------------|----------------------|---|
| Power Tools | Satisfactory | | - |
| Hand Tools | Satisfactory | | - |
| Power Saws | Satisfactory | | - |
| Personal Protective Equipment | Unsatisfactory | | - |
| Electrical Safety | Satisfactory | | - |
| Trenching/Excavation | N/A | | - |
| Confined Space | N/A | | - |
| Fall Protection | N/A | | - |
| Ladder Safety | Unsatisfactory | | - |
| Access/Egress | Unsatisfactory | | - |
| Stairway/Ramps/Runways | Unsatisfactory | See access comments. | - |
| Heavy Equipment | N/A | | - |
| Crane/Rigging | Unsatisfactory | | - |
| Powder Actuated Tools | N/A | | - |
| Cylinder Storage | N/A | | - |
| Floor/Roof/Wall Openings | Satisfactory | | - |
| Railing | Unsatisfactory | | - |
| Material Storage | Satisfactory | | - |
| Impalement Hazards | Unsatisfactory | | - |
| Traffic Control | N/A | | - |
| Scissor Lifts/Boom Lift | N/A | | - |
| Powered Industrial Trucks | N/A | | - |
| Scaffolding/Shoring | N/A | | - |
| Suspended Scaffolding | N/A | | - |
| Silica Items/Dust | N/A | | - |
| Hot Work | N/A | | - |
| Housekeeping | Satisfactory | | - |
| Roofing Operations | N/A | | - |
| Demolition | N/A | | - |

UNSATISFACTORY ITEMS

Photo Comment Corrective Action

| | An employee is using a nail gun while not wearing safety glasses. | Please ensure employees use ANSI Z87+ safety glasses while using a nail gun. |
|---|--|---|
| | An employee is using a nail gun while not wearing safety glasses. | Please ensure employees use ANSI Z87+ safety glasses while using a nail gun. |
| | An employee is using an A-Frame ladder in a closed position, which is prohibited. | Please ensure employees use A-Frame ladders in an open, locked, and level position. |
| | A second set of stairs has not yet been completed to the top floor. | Prior to raising studs to the 3rd floor 2 sets of stairs must be completed. The superintendent reported the stairs will be completed this week. |
| - | | |
| | An employee is using a Manitou that is classified as a crane due to its attachment configuration and capacity. The employee does not have a crane certification. | Please ensure an employee that is a certified crane operator is operating the Manitou. |



Guardrails exceed 8' between vertical posts.

Please ensure vertical posts span no more than 8'.



There is uncapped rebar next to a walkway.

Please ensure impalement protection is provided by capping or covering the rebar.