







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Helio	Type of Inspection:	SCC USE ONLY: General Contractor Review
Project	Arya	Date of Inspection	March 14, 2022
Inspector Name	Jeremy Chavez	Time of Inspection	10:35 AM

INSPECTION ITEMS

Item		Comment	Photo
Safety Manual	Satisfactory		-
Tailgate Meetings	Satisfactory		-
SDS	Satisfactory		-
Daily Inspection	Satisfactory		-
Sub-Contractor Meetings	Satisfactory		-
Labor Law Posters	Satisfactory		-
Codes/Emergency Posters	Satisfactory		-
Permits	Satisfactory		-
Fire Extinguisher	Satisfactory		-
Building Fire Extinguisher	N/A		-
First Aid Kit	Satisfactory		-
First Aid/CPR Cert	Satisfactory		-
Restrooms/Wash Stations	Satisfactory	Restrooms and wash stations are well maintained. Excellent job!	
Waste Containers	Satisfactory		-
Water Supply	Satisfactory		-
Shade	Satisfactory		-
Power Tools	N/A		-
Hand Tools	N/A		-
Power Saws	N/A		-
Personal Protective Equipment	Satisfactory		-

Electrical Safety	N/A		-
Trenching/Excavation	Satisfactory		-
Confined Space	N/A		-
Fall Protection	N/A		-
Ladder Safety	N/A		-
Access/Egress	Satisfactory		-
Stairway/Ramps/Runways	Satisfactory		-
Heavy Equipment	Satisfactory	Equipment operations were observed to be safe. As a general reminder, please ensure operators are certified and a daily equipment inspection is documented.	
Crane/Rigging	N/A		-
Powder Actuated Tools	N/A		-
Cylinder Storage	N/A		-
Floor/Roof/Wall Openings	N/A		-
Railing	Satisfactory	Guardrails have been installed where required. Great work!	
Material Storage	N/A		-
Impalement Hazards	N/A		-
Traffic Control	Unsatisfactory		-
Scissor Lifts/Boom Lift	N/A		-
Powered Industrial Trucks	N/A		-
Scaffolding/Shoring	N/A		-
Suspended Scaffolding	N/A		-
Silica Items/Dust	N/A		-
Hot Work	N/A		-
Housekeeping	Satisfactory	Excellent job with housekeeping throughout the project. Today dirt is being hauled away.	
Roofing Operations	N/A		-
Demolition	N/A		-

UNSATISFACTORY ITEMS

Photo

Comment

Corrective Action



An employee is flagging without the required equipment, which includes the STOP/SLOW paddle attached to a staff so as to have the bottom of the sign at a height of 6'.

Please ensure the STOP/SLOW paddle is configured to a 6' staff as described above.