







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Helio	Type of Inspection:	SCC USE ONLY: General Contractor Review
Project	Arya	Date of Inspection	June 22, 2022
Inspector Name	Jeremy Chavez	Time of Inspection	09:00 AM

INSPECTION ITEMS

Item		Comment	Photo
Safety Manual	Satisfactory		-
Tailgate Meetings	Satisfactory		-
SDS	N/A		-
Daily Inspection	Satisfactory		-
Sub-Contractor Meetings	N/A		-
Labor Law Posters	Unsatisfactory		-
Codes/Emergency Posters	N/A	See Labor Law comments.	-
Permits	N/A	Discussed obtaining the Project Permit.	-
Fire Extinguisher	Unsatisfactory		
Building Fire Extinguisher	N/A		-
First Aid Kit	Satisfactory	Great work ensuring a first aid kit has been provided for the project.	
First Aid/CPR Cert	Satisfactory		-
Restrooms/Wash Stations	Satisfactory	Restrooms appear to be maintained in a sanitary condition. Good job.	
Waste Containers	Satisfactory		-

Water Supply	Satisfactory		-
Shade	Satisfactory		-
Power Tools	Satisfactory		-
Hand Tools	Satisfactory		-
Power Saws	N/A		-
Personal Protective Equipment	Satisfactory		-
Electrical Safety	Satisfactory		-
Trenching/Excavation	N/A		-
Confined Space	N/A		-
Fall Protection	N/A		-
Ladder Safety	N/A		-
Access/Egress	Satisfactory		-
Stairway/Ramps/Runways	Satisfactory		-
Heavy Equipment	N/A		-
Crane/Rigging	N/A		-
Powder Actuated Tools	N/A		-
Cylinder Storage	N/A		-
Floor/Roof/Wall Openings	N/A		-
Railing	Satisfactory	Railing has been installed where required. Excellent job!	
Material Storage	Satisfactory		-
Impalement Hazards	Unsatisfactory		-
Traffic Control	N/A		-
Scissor Lifts/Boom Lift	N/A		-
Powered Industrial Trucks	N/A		-
Scaffolding/Shoring	N/A		-
Suspended Scaffolding	N/A		-
Silica Items/Dust	N/A		-
Hot Work	N/A		-
Housekeeping	Satisfactory		-
Roofing Operations	N/A		-
Demolition	N/A		-

UNSATISFACTORY ITEMS

Photo

Comment

Corrective Action



There has been improvements regarding providing the required postings, however there are a few more documents that need to be posted.

Please ensure the following are provided; Operating Rules for Industrial Trucks, emergency numbers, Cal OSHA's Heat Illness poster, the Heat Illness Prevention Program, and the Code of Safe Practices.



The pictured fire extinguisher is not mounted 3-5' in height with signage that identifies its location. It also does not have an inspection tag.

Please ensure fire extinguishers are mounted 3-5' in height, have signage, and have their inspection tag (annual and monthly).



Pictured is rebar that has not been capped or covered.

Please ensure rebar that is below 6' in height is capped or covered.