










PROJECT INSPECTION


Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Helio	Type of Inspection:	SCC USE ONLY: General Contractor Review
Project	Canfield	Date of Inspection	February 07, 2023
Inspector Name	Jeremy Chavez	Time of Inspection	09:35 AM

INSPECTION ITEMS

Item		Comment	Photo
Safety Manual	Satisfactory		-
Tailgate Meetings	Satisfactory		-
SDS	Satisfactory		-
Daily Inspection	Satisfactory	The superintendent continues to document the daily inspection report.	
Sub-Contractor Meetings	N/A		-
Labor Law Posters	Satisfactory		-
Codes/Emergency Posters	Satisfactory		-
Permits	Satisfactory		-
Fire Extinguisher	Satisfactory	Good job inspecting fire extinguishers monthly.	
Building Fire Extinguisher	Satisfactory		-
First Aid Kit	Satisfactory		-
First Aid/CPR Cert	Satisfactory		-
Restrooms/Wash Stations	Satisfactory	Restrooms and wash stations appeared to be maintained in a sanitary condition.	
Waste Containers	Satisfactory		-
Water Supply	Satisfactory		-

Shade	Satisfactory		-
Power Tools	Satisfactory		-
Hand Tools	Satisfactory		-
Power Saws	Satisfactory		-
Personal Protective Equipment	Satisfactory	Employees were observed wearing the required PPE, including safety glasses.	
Electrical Safety	Satisfactory		-
Trenching/Excavation	N/A		-
Confined Space	N/A		-
Fall Protection	N/A		-
Ladder Safety	Satisfactory	Safe work practices were observed while employees were using ladders.	
Access/Egress	Satisfactory	Stairs have been completed to the top floor. Excellent job.	
Stairway/Ramps/Runways	Satisfactory		-
Heavy Equipment	N/A		-
Crane/Rigging	N/A		-
Powder Actuated Tools	N/A		-
Cylinder Storage	N/A		-
Floor/Roof/Wall Openings	Satisfactory		-
Railing	Unsatisfactory	One area was noted where railing was missing. Please ensure guardrails are installed.	
Material Storage	Satisfactory		-
Impalement Hazards	N/A		-
Traffic Control	N/A		-
Scissor Lifts/Boom Lift	N/A		-
Powered Industrial Trucks	N/A		-
Scaffolding/Shoring	Satisfactory		-
Suspended Scaffolding	N/A		-

Silica Items/Dust	N/A		-
Hot Work	N/A		-
Housekeeping	Satisfactory	Excellent job with housekeeping throughout the project.	
Roofing Operations	N/A		-
Demolition	N/A		-

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
-		