







# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Helio	<b>Type of Inspection:</b>	SCC USE ONLY: General Contractor Review
<b>Project</b>	Canfield	<b>Date of Inspection</b>	May 02, 2023
<b>Inspector Name</b>	Jeremy Chavez	<b>Time of Inspection</b>	09:00 AM

## INSPECTION ITEMS

Item		Comment	Photo
Safety Manual	Satisfactory		-
Tailgate Meetings	Satisfactory		-
SDS	Satisfactory		-
Daily Inspection	Satisfactory	Daily job site inspections continue to be completed.	
Sub-Contractor Meetings	N/A		-
Labor Law Posters	Satisfactory		-
Codes/Emergency Posters	Satisfactory		-
Permits	Satisfactory		-
Fire Extinguisher	Satisfactory		-
Building Fire Extinguisher	Satisfactory		-
First Aid Kit	Satisfactory		-
First Aid/CPR Cert	Satisfactory		-
Restrooms/Wash Stations	Satisfactory	Restrooms are maintained in a sanitary condition.	

Waste Containers	Satisfactory		-
Water Supply	Satisfactory		-
Shade	Satisfactory		-
Power Tools	Satisfactory		-
Hand Tools	Satisfactory		-
Power Saws	Satisfactory		-
Personal Protective Equipment	Satisfactory	Employees were observed wearing the required PPE, including a hard hat and safety glasses.	
Electrical Safety	Unsatisfactory	A section of stairs had insufficient illumination. The superintendent will ensure string lights are provided for the area.	
Trenching/Excavation	N/A		-
Confined Space	N/A		-

## UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
-		