







PROJECT INSPECTION


Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Helio	Type of Inspection:	SCC USE ONLY: General Contractor Review
Project	Canfield	Date of Inspection	June 22, 2022
Inspector Name	Jeremy Chavez	Time of Inspection	09:30 AM

INSPECTION ITEMS

Item		Comment	Photo
Safety Manual	Satisfactory		-
Tailgate Meetings	Satisfactory	The superintendent is in the process of obtaining this week's tailgate meeting from sub contractors.	-
SDS	Satisfactory		-
Daily Inspection	Satisfactory		-
Sub-Contractor Meetings	N/A		-
Labor Law Posters	Satisfactory	Excellent job providing the required jobsite postings.	
Codes/Emergency Posters	Satisfactory		-
Permits	N/A	The superintendent is in the process of obtaining a Project Permit.	-
Fire Extinguisher	Satisfactory		-
Building Fire Extinguisher	N/A		-
First Aid Kit	Satisfactory	A first aid kits has been provided for the project.	
First Aid/CPR Cert	N/A		-

Restrooms/Wash Stations	Satisfactory	Restrooms and wash stations appeared to be maintained in a sanitary condition.	
Waste Containers	Satisfactory		-
Water Supply	Satisfactory		-
Shade	Satisfactory		-
Power Tools	N/A		-
Hand Tools	Satisfactory		-
Power Saws	N/A		-
Personal Protective Equipment	Satisfactory		-
Electrical Safety	N/A		-
Trenching/Excavation	Satisfactory		-
Confined Space	N/A		-
Fall Protection	N/A		-
Ladder Safety	Satisfactory		-
Access/Egress	Satisfactory		-
Stairway/Ramps/Runways	N/A		-
Heavy Equipment	Satisfactory	As a general reminder, please ensure equipment has a documented daily inspection.	
Crane/Rigging	N/A		-
Powder Actuated Tools	N/A		-
Cylinder Storage	N/A		-
Floor/Roof/Wall Openings	N/A		-
Railing	N/A		-
Material Storage	Satisfactory		-
Impalement Hazards	N/A		-
Traffic Control	N/A		-
Scissor Lifts/Boom Lift	N/A		-
Powered Industrial Trucks	N/A		-
Scaffolding/Shoring	N/A		-
Suspended Scaffolding	N/A		-
Silica Items/Dust	Satisfactory		-
Hot Work	N/A		-

Housekeeping	Satisfactory	Flammable liquids were observed to be contained in the required container. Excellent job.	
Roofing Operations	N/A		-
Demolition	N/A		-