








PROJECT INSPECTION


Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Helio	Type of Inspection:	SCC USE ONLY: General Contractor Review
Project	Canfield	Date of Inspection	July 05, 2022
Inspector Name	Jeremy Chavez	Time of Inspection	10:15 AM

INSPECTION ITEMS

Item		Comment	Photo
Safety Manual	Satisfactory		-
Tailgate Meetings	Satisfactory	Superintendent is waiting for today's meeting to be submitted to him.	-
SDS	N/A		-
Daily Inspection	Satisfactory		-
Sub-Contractor Meetings	N/A		-
Labor Law Posters	Satisfactory	Good job maintaining jobsite postings. The Heat Illness Prevention Program is posted in the office.	
Codes/Emergency Posters	Satisfactory		-
Permits	N/A	The superintendent has an appointment to obtain the Project Permit.	-
Fire Extinguisher	Satisfactory		-
Building Fire Extinguisher	N/A		-
First Aid Kit	Satisfactory		-
First Aid/CPR Cert	N/A	Superintendent is in need of a CPR certification course.	-
Restrooms/Wash Stations	Satisfactory		-
Waste Containers	Satisfactory		-
Water Supply	Satisfactory	As a general reminder, 2 gallons per employee of potable water is required to be on site.	-

Shade	Satisfactory	A pop up umbrella and trees are currently being used as shade. The superintendent reported a pop up tent will also be provided this week.	
Power Tools	Satisfactory		-
Hand Tools	Satisfactory		-
Power Saws	Satisfactory	Tools observed had the manufacturer's safety elements present and unaltered.	
Personal Protective Equipment	Satisfactory		-
Electrical Safety	Satisfactory		-
Trenching/Excavation	N/A		-
Confined Space	N/A		-
Fall Protection	N/A		-
Ladder Safety	N/A		-
Access/Egress	N/A		-
Stairway/Ramps/Runways	N/A		-
Heavy Equipment	N/A		-
Crane/Rigging	N/A		-
Powder Actuated Tools	N/A		-
Cylinder Storage	N/A		-
Floor/Roof/Wall Openings	N/A		-
Railing	N/A		-
Material Storage	Satisfactory		-
Impalement Hazards	Satisfactory	The foreman is currently installing rebar caps where needed. Good job.	
Traffic Control	N/A		-
Scissor Lifts/Boom Lift	N/A		-
Powered Industrial Trucks	Satisfactory	As a general reminder, please ensure a daily inspection form is documented when the reach lift is used.	
Scaffolding/Shoring	N/A		-
Suspended Scaffolding	N/A		-

Silica Items/Dust	N/A		-
Hot Work	N/A		-
Housekeeping	Satisfactory	Debris is collected into piles before being discarded. Good job.	
Roofing Operations	N/A		-
Demolition	N/A		-