

## **PROJECT INSPECTION**

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Helio	Type of Inspection:	SCC USE ONLY: General Contractor Review
Project	Venue	Date of Inspection	October 04, 2021
Inspector Name	Jeremy Chavez	Time of Inspection	09:30 AM

## **INSPECTION ITEMS**

Item		Comment	Photo
Safety Manual	Satisfactory		-
Tailgate Meetings	Satisfactory		-
SDS	Satisfactory		-
Daily Inspection	Satisfactory		-
Sub-Contractor Meetings	Satisfactory		-
Labor Law Posters	Satisfactory		-
Codes/Emergency Posters	Satisfactory		-
Permits	Satisfactory		-
Fire Extinguisher	Satisfactory		-
Building Fire Extinguisher	Satisfactory		-
First Aid Kit	Satisfactory		-
First Aid/CPR Cert	Satisfactory		-
Restrooms/Wash Stations	Satisfactory		-
Waste Containers	Satisfactory		-
Water Supply	Unsatisfactory		-
Shade	Satisfactory		-
Power Tools	Satisfactory	All tools observed had the manufacturer's guard present and unaltered. Good job.	
Hand Tools	Satisfactory		-
Power Saws	Satisfactory		-
Personal Protective Equipment	Unsatisfactory		-

Electrical Safety	Satisfactory -	
Trenching/Excavation	N/A -	
Confined Space	N/A -	
Fall Protection	N/A -	
Ladder Safety	Unsatisfactory -	
Access/Egress	Satisfactory -	
Stairway/Ramps/Runways	Unsatisfactory -	
Heavy Equipment	N/A -	
Crane/Rigging	N/A -	
Powder Actuated Tools	N/A -	
Cylinder Storage	Satisfactory -	
Floor/Roof/Wall Openings	Satisfactory -	
Railing	Satisfactory -	
Material Storage	Satisfactory -	
Impalement Hazards	Satisfactory -	
Traffic Control	N/A -	
Scissor Lifts/Boom Lift	N/A -	
Powered Industrial Trucks	Satisfactory -	
Scaffolding/Shoring	Satisfactory -	
Suspended Scaffolding	N/A -	
Silica Items/Dust	Satisfactory -	
Hot Work	N/A -	
Housekeeping	Satisfactory -	
Roofing Operations	N/A -	
Demolition	N/A -	

## UNSATISFACTORY ITEMS

Photo Comment Corrective Action



Employees are sharing a 5 gallon water container.

Due to coronavirus precautions, please ensure individual containers, such as water bottles, are used.

