








PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Helio	Type of Inspection:	SCC USE ONLY: General Contractor Review
Project	Venue	Date of Inspection	February 15, 2022
Inspector Name	Jeremy Chavez	Time of Inspection	08:50 AM

INSPECTION ITEMS

Item		Comment	Photo
Safety Manual	Satisfactory		-
Tailgate Meetings	Satisfactory		-
SDS	Satisfactory		-
Daily Inspection	Satisfactory		-
Sub-Contractor Meetings	Satisfactory		-
Labor Law Posters	Satisfactory		-
Codes/Emergency Posters	Satisfactory		-
Permits	Satisfactory		-
Fire Extinguisher	Satisfactory		-
Building Fire Extinguisher	Satisfactory		-
First Aid Kit	Satisfactory		-
First Aid/CPR Cert	Satisfactory		-
Restrooms/Wash Stations	Satisfactory		-
Waste Containers	Satisfactory		-
Water Supply	Satisfactory		-
Shade	Satisfactory		-
Power Tools	Satisfactory	All tools observed had the manufacturer's guard present and unaltered. Good work.	
Hand Tools	Satisfactory		-
Power Saws	Satisfactory		-
Personal Protective Equipment	Unsatisfactory		-

Electrical Safety	Satisfactory		-
Trenching/Excavation	N/A		-
Confined Space	N/A		-
Fall Protection	N/A		-
Ladder Safety	Satisfactory		-
Access/Egress	Satisfactory		-
Stairway/Ramps/Runways	Satisfactory		-
Heavy Equipment	N/A		-
Crane/Rigging	N/A		-
Powder Actuated Tools	N/A		-
Cylinder Storage	N/A		-
Floor/Roof/Wall Openings	Satisfactory		-
Railing	Satisfactory	Railing was installed where required, such as at this elevator shaft. Excellent job maintaining guardrails throughout the project.	
Material Storage	Satisfactory	This is a great example of securing drywall from tipping, sliding, or falling. Keep up the great work!	
Impalement Hazards	Satisfactory		-
Traffic Control	Satisfactory		-
Scissor Lifts/Boom Lift	Satisfactory		-
Powered Industrial Trucks	N/A		-
Scaffolding/Shoring	Satisfactory	A reminder was given that stilts are not permitted to be used in California. Employees had not used the stilts and only had them staged. They were immediately removed from the project.	
Suspended Scaffolding	N/A		-
Silica Items/Dust	Satisfactory		-
Hot Work	N/A		-
Housekeeping	Satisfactory	Excellent job with illumination and housekeeping on the the project.	
Roofing Operations	N/A		-
Demolition	N/A		-

UNSATISFACTORY ITEMS

Photo

Comment

Corrective Action



Employee is using a nail gun while not wearing safety glasses. Employee does not have safety glasses on his person.

Employees must wear their safety glasses when required, such as when using power tools or near employees using power tools.