







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Helio	Type of Inspection:	SCC USE ONLY: General Contractor Review
Project	Venue	Date of Inspection	February 21, 2023
Inspector Name	Jeremy Chavez	Time of Inspection	11:00 AM

INSPECTION ITEMS

Item		Comment	Photo
Safety Manual	Satisfactory		-
Tailgate Meetings	N/A	The superintendent is confirming contractors have submitted their tailgate meetings.	-
SDS	Satisfactory		-
Daily Inspection	N/A	The superintendent is in the process of updating records of inspections performed.	-
Sub-Contractor Meetings	N/A		-
Labor Law Posters	Satisfactory		-
Codes/Emergency Posters	Satisfactory		-
Permits	Satisfactory		-
Fire Extinguisher	Satisfactory		-
Building Fire Extinguisher	Satisfactory		-
First Aid Kit	Satisfactory		-
First Aid/CPR Cert	Satisfactory		-
Restrooms/Wash Stations	Satisfactory		-
Waste Containers	Satisfactory		-
Water Supply	Satisfactory		-
Shade	Satisfactory		-
Power Tools	Unsatisfactory	An employee was observed using a grinder that does not have its guard equipped. Please ensure employees operate tools with the manufacturer's required guard present and unaltered.	

Hand Tools	Satisfactory		-
Power Saws	Satisfactory		-
Personal Protective Equipment	Satisfactory		-
Electrical Safety	Satisfactory	Lighting, especially in the stairs, is improving. Good job.	
Trenching/Excavation	N/A		-
Confined Space	N/A		-
Fall Protection	N/A	Good job posting signage at the entrance to balconies where the permanent railing has not been installed.	
Ladder Safety	Satisfactory	Safe work practices were observed while employees were using ladders.	
Access/Egress	Satisfactory		-
Stairway/Ramps/Runways	Satisfactory		-
Heavy Equipment	N/A		-
Crane/Rigging	N/A		-
Powder Actuated Tools	N/A		-
Cylinder Storage	N/A		-
Floor/Roof/Wall Openings	Satisfactory		-

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
-		