





PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com



Company	Helio	Type of Inspection:	General Construction
Project	Venue	Date of Inspection	March 01, 2021
Inspector Name	Jeremy Chavez	Time of Inspection	11:30 AM

INSPECTION ITEMS

Item		Comment	Photo
is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory		-
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory		-
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory		-
Are emergency and labor law postings in place?	Satisfactory		-
Is Personal Protective Equipment being worn as required?	Unsatisfactory		-
Are scaffolding safety procedures being followed?	N/A		-
Are hand and power tools being used safely?	Satisfactory		-
Is good housekeeping being maintained?	Satisfactory		-
Is fall protection in place where required?	N/A		-
Is trenching & excavation work being done safely?	Satisfactory		-
Are confined space safety procedures being followed?	N/A		-
Are scissor lifts / elevated platforms being used safely?	N/A		-
Are boom lifts and other aerial devices being used safely?	N/A		-

Is heavy equipment being used safely?	Satisfactory	Equipment certifications were submitted. Excellent work.	
Are electrical items being used safely?	Satisfactory		-
Are roofing operations being performed safely?	N/A		-
Is demolition work being done safely?	N/A		-
Are all other tasks being performed safely?	Satisfactory	Great job with dust control.	

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
	Face coverings are not being worn when required.	Face coverings were put on.
	Please ensure that the PPE recommended by the manufacturer is used. This generally includes hearing protection, a face shield, and heavy duty gloves (e.g. leather gloves).	See comments above.