






PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Helio	Type of Inspection:	SCC USE ONLY: General Contractor Review
Project	Venue	Date of Inspection	March 01, 2022
Inspector Name	Jeremy Chavez	Time of Inspection	09:20 AM

INSPECTION ITEMS

Item		Comment	Photo
Safety Manual	Satisfactory		-
Tailgate Meetings	Satisfactory		-
SDS	Satisfactory		-
Daily Inspection	Satisfactory		-
Sub-Contractor Meetings	Satisfactory		-
Labor Law Posters	Satisfactory		-
Codes/Emergency Posters	Satisfactory		-
Permits	Satisfactory		-
Fire Extinguisher	Satisfactory		-
Building Fire Extinguisher	Satisfactory		-
First Aid Kit	Satisfactory		-
First Aid/CPR Cert	Satisfactory		-
Restrooms/Wash Stations	Satisfactory		-
Waste Containers	Satisfactory		-
Water Supply	Satisfactory	There is plenty of cool potable water located throughout the project.	
Shade	Satisfactory		-
Power Tools	Satisfactory		-
Hand Tools	Satisfactory		-
Power Saws	Satisfactory		-

Personal Protective Equipment	Satisfactory	Employees were observed wearing the required PPE, including ANSI rated safety glasses.	
Electrical Safety	Satisfactory		-
Trenching/Excavation	N/A		-
Confined Space	N/A		-
Fall Protection	Satisfactory		-
Ladder Safety	Satisfactory		-
Access/Egress	Satisfactory		-
Stairway/Ramps/Runways	Satisfactory		-
Heavy Equipment	N/A		-
Crane/Rigging	Satisfactory		-
Powder Actuated Tools	N/A		-
Cylinder Storage	N/A		-
Floor/Roof/Wall Openings	Satisfactory		-
Railing	Satisfactory		-
Material Storage	Satisfactory	Excellent job with material storage throughout the project.	
Impalement Hazards	Satisfactory		-
Traffic Control	Satisfactory		-
Scissor Lifts/Boom Lift	Satisfactory		-
Powered Industrial Trucks	Satisfactory		-
Scaffolding/Shoring	Satisfactory		-
Suspended Scaffolding	N/A		-
Silica Items/Dust	Satisfactory		-
Hot Work	N/A		-
Housekeeping	Satisfactory		-
Roofing Operations	N/A		-
Demolition	N/A		-

UNSATISFACTORY ITEMS

Photo

Comment

Corrective Action



An employee was heading to use a grinder without a guard.

Reminders were given that all tools must have the manufacturer's guard present. The employee went back to his tool bag and equipped the guard.



Employees are working above their trigger height and within 6' of an unprotected edge. This exposed them to a significant fall hazard.

The employees complied to don their personal fall protection equipment.



An employee is surfing a mobile scaffold that is above 4' in height.

Employees are not permitted to surf or scot mobile scaffolds of 4' in height or higher. All 4 casters must be locked. The employee complied to lock the casters.