







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com



Company	Helio	Type of Inspection:	General Construction
Project	Venue	Date of Inspection	March 17, 2021
Inspector Name	Jeremy Chavez	Time of Inspection	10:30 AM

INSPECTION ITEMS

Item		Comment	Photo
is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory		-
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory		-
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory		-
Are emergency and labor law postings in place?	Satisfactory		-
Is Personal Protective Equipment being worn as required?	Unsatisfactory		-
Are scaffolding safety procedures being followed?	N/A		-
Are hand and power tools being used safely?	Satisfactory	All tools observed had the manufacturer's guard present and unaltered. Excellent job.	
Is good housekeeping being maintained?	Satisfactory		-
Is fall protection in place where required?	N/A		-
Is trenching & excavation work being done safely?	Satisfactory		-
Are confined space safety procedures being followed?	N/A		-
Are scissor lifts / elevated platforms being used safely?	N/A		-
Are boom lifts and other aerial devices being used safely?	N/A		-

Is heavy equipment being used safely?	Satisfactory	Great job with seatbelt use and equipment operations.	
Are electrical items being used safely?	Satisfactory		
Are roofing operations being performed safely?	N/A		-
Is demolition work being done safely?	N/A		-
Are all other tasks being performed safely?	Satisfactory	Restrooms and wash stations were well maintained.	

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
	Employee is not wearing safety glasses when using a skill saw.	Employee donned safety glasses.
	Employee is not wearing a face covering when required.	Employee donned his face covering.