





# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Helio	<b>Type of Inspection:</b>	SCC USE ONLY: General Contractor Review
<b>Project</b>	Venue	<b>Date of Inspection</b>	March 21, 2022
<b>Inspector Name</b>	Jeremy Chavez	<b>Time of Inspection</b>	11:00 AM

## INSPECTION ITEMS

Item		Comment	Photo
Safety Manual	Satisfactory		-
Tailgate Meetings	Satisfactory		-
SDS	Satisfactory		-
Daily Inspection	Satisfactory		-
Sub-Contractor Meetings	Satisfactory		-
Labor Law Posters	Satisfactory		-
Codes/Emergency Posters	Satisfactory		-
Permits	Satisfactory		-
Fire Extinguisher	Satisfactory		-
Building Fire Extinguisher	Satisfactory		-
First Aid Kit	Satisfactory		-
First Aid/CPR Cert	Satisfactory		-
Restrooms/Wash Stations	Satisfactory		-
Waste Containers	Satisfactory		-
Water Supply	Satisfactory		-
Shade	Satisfactory		-
Power Tools	Satisfactory	Tools observed had the manufacturer's safety elements present and unaltered. Good job.	
Hand Tools	Satisfactory		-
Power Saws	Satisfactory		-
Personal Protective Equipment	Unsatisfactory		-

Electrical Safety	Satisfactory		-
Trenching/Excavation	N/A		-
Confined Space	N/A		-
Fall Protection	Unsatisfactory		-
Ladder Safety	Satisfactory		-
Access/Egress	Unsatisfactory		-
Stairway/Ramps/Runways	Satisfactory		-
Heavy Equipment	N/A		-
Crane/Rigging	Unsatisfactory		-
Powder Actuated Tools	N/A		-
Cylinder Storage	N/A		-
Floor/Roof/Wall Openings	Satisfactory		-
Railing	Satisfactory		-
Material Storage	Satisfactory		-
Impalement Hazards	Satisfactory		-
Traffic Control	Satisfactory		-
Scissor Lifts/Boom Lift	N/A		-
Powered Industrial Trucks	Satisfactory		-
Scaffolding/Shoring	Satisfactory		-
Suspended Scaffolding	N/A		-
Silica Items/Dust	Satisfactory		-
Hot Work	N/A		-
Housekeeping	Satisfactory	Excellent job with housekeeping throughout the project.	
Roofing Operations	N/A		-
Demolition	N/A		-

## UNSATISFACTORY ITEMS

Photo

Comment

Corrective Action



Employee in the foreground was observed using a skill saw while not wearing safety glasses.

Employees must wear ANSI rated safety glasses when operating power tools.



Employee is using a nail gun while not wearing safety glasses.

Employees must wear their safety glasses while using a nail gun.



Employee is working above his trigger height and exposed to a significant fall hazard.

Employees must have a means of fall protection, such as personal fall protection. Alternatively guardrails may be installed. Employees are in the process of installing guardrails, however have not completed the installation on this level. As a note, employees installing railing will need to use personal fall protection.



Stairs have not been installed to the top floor which creates an access issue in the event of an emergency.

As pictured, the stairs are in the process of being installed. Please ensure this is provided as soon as possible.



Employees are hoisting materials while a tag line is not in use.

Loads must have a tagline to prevent twisting, turning, or tipping, especially consider wind conditions today.