



# ACCIDENT/ INCIDENT INVESTIGATION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Helio	<b>Project</b>	Venue
<b>Date of Incident</b>	June 24, 2021	<b>Time of Incident</b>	12:15 PM
<b>Date of Investigation</b>	June 24, 2021	<b>Time of Investigation</b>	12:30 PM
<b>Investigator</b>	Eric Williams	<b>Type of Incident</b>	Injury

## EMPLOYEE INFORMATION

**Employee Name**

Andrew S.

**Nature Of Injury**

Cut leg with hole saw

## DESCRIPTION OF INCIDENT

Plumber was cutting openings in the bottom plate of walls on the 2nd floor framing. While using the drill motor with a hog bit, He accidentally pressed the trigger, then hit the wood which cause the bit to grab/cut his leg. He was taken to the hospital by ambulance and the wound required stitches.


## WITNESSES & STATEMENTS

**Name****Company****Statement**


## COMMENTS & PHOTOS

**comment**


- Location of incident

**Image**

- Tool worker was using during incident



- Firefighters removing patient from the 2nd floor of Building B



## ROOT CAUSE

Operator Error

## CONTRIBUTING FACTORS

N/A

## INVESTIGATOR SIGNATURE

## CORRECTIVE ACTION

Reminded all workers how important it is to use caution while working with power tools.

## ADDITIONAL INFORMATION

Patients Injury required stitches and he was released from the hospital same day.