



# ACCIDENT/ INCIDENT INVESTIGATION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Helio	<b>Project</b>	Venue
<b>Date of Incident</b>	November 30, 2021	<b>Time of Incident</b>	12:34 PM
<b>Date of Investigation</b>	November 30, 2021	<b>Time of Investigation</b>	12:34 PM
<b>Investigator</b>	Eric Williams	<b>Type of Incident</b>	Injury

## EMPLOYEE INFORMATION

**Employee Name**

Mitchell

**Nature Of Injury**

injured Thumb

## DESCRIPTION OF INCIDENT

Right hand thumb was injured.

## WITNESSES & STATEMENTS

<b>Name</b>	<b>Company</b>	<b>Statement</b>
Beto Mitchell Foreman	Mitchell Brothers Concrete	Removing concrete shoring and injured right hand thumb.

## COMMENTS & PHOTOS

**comment**

-injured thumb cleaned and dressed

**Image**

## ROOT CAUSE

Hand was in the way and injured

## CONTRIBUTING FACTORS

Operator error

## INVESTIGATOR SIGNATURE



## CORRECTIVE ACTION

Told employee to Be careful when removing shoring. Move important members of hand out of the way of heavy objects.

## ADDITIONAL INFORMATION

N/A