



ACCIDENT/ INCIDENT INVESTIGATION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Helio	Project	Venue
Date of Incident	September 23, 2022	Time of Incident	10:15 AM
Date of Investigation	September 23, 2022	Time of Investigation	10:30 AM
Investigator	Adam Martin	Type of Incident	Injury

EMPLOYEE INFORMATION

Employee Name

Manuel Contreras

Nature Of Injury

fall due to snapped scaffold plank

DESCRIPTION OF INCIDENT

AA Gonzalez plaster foreman Manuel Contreras was working on a scaffold platform when a plank broke in half. Manuel fell approximately 7 feet and landed on scaffold planks below. Injuries include scrapes on left elbow as well as soreness on left rib cage. Manuel stated is hurt when breathing. Manuel was directed to go get checked out by a doctor per his Supervisor and Helio field Superintendent Adam Martin.


WITNESSES & STATEMENTS

Name	Company	Statement
Herman Barajas	AA Gonzalez	Both we're working on the same platform when Manuel's plank broke. Manuel fell down to the next level injuring his ribs and left elbow

COMMENTS & PHOTOS

comment

Image






ROOT CAUSE

Faulty scaffold plank

CONTRIBUTING FACTORS

None known at this time

INVESTIGATOR SIGNATURE

A handwritten signature in black ink, appearing to be 'D. M. A.', located in the upper left quadrant of the page.

CORRECTIVE ACTION

Removed the broken plank. Notified scaffold company to come and inspect entire scaffold system. They replied they would be here first thing Monday 9/26/22. Directed Manuel to go to the Doctor for evaluation.

ADDITIONAL INFORMATION

-