



PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Humphrey Plumbing	Type of Inspection:	General Construction
Project	Devonwood	Date of Inspection	April 01, 2021
Inspector Name	Jesus Rivas	Time of Inspection	04:37 PM

INSPECTION ITEMS

Item		Comment	Photo
is emergency equipment available, including first aid kit(s) and fire extinguisher(s)?	Satisfactory		-
Is safety documentation available (Written Safety Programs, SDS, Tailgate Meetings)	Satisfactory		-
Is drinking water and shade set up sufficient for the amount of workers?	Satisfactory		-
Are emergency and labor law postings in place?	Satisfactory		-
Is Personal Protective Equipment being worn as required?	Satisfactory		-
Are scaffolding safety procedures being followed?	Satisfactory		-
Are hand and power tools being used safely?	Satisfactory		-
Is good housekeeping being maintained?	Satisfactory		-
Is fall protection in place where required?	Satisfactory		-
Is trenching & excavation work being done safely?	Satisfactory		-
Are confined space safety procedures being followed?	Satisfactory		-
Are scissor lifts / elevated platforms being used safely?	N/A		-
Are boom lifts and other aerial devices being used safely?	N/A		-
Is heavy equipment being used safely?	N/A		-
Are electrical items being used safely?	Satisfactory		-

Are roofing operations being performed safely?	Satisfactory		-
Is demolition work being done safely?	Satisfactory		-
Are all other tasks being performed safely?	Satisfactory		-