

EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Humphrey Plumbing	Type of Inspection:	Truck 73
Project	Laguna Ranch II	Date of Inspection	May 03, 2023
Inspector Name	Juan Gutierrez	Time of Inspection	11:41 AM

INSPECTION ITEMS

Item		Comment	Photo
Click "Satisfactory" and enter the VEHICLE NUMBER or LICENSE PLATE in the comments section below	Satisfactory		-
Click "Satisfactory" and enter the ODOMETER reading in the comments section below	Satisfactory		-
Is the vehicle free of any unusual noises?	Satisfactory		-
Gauges: Is the fuel gauge working correctly?	Satisfactory		-
Gauges: Is the temperature gauge working correctly?	Satisfactory		-
Gauges: Is the dashboard warning light working correctly?	Satisfactory		-
Lights: Are the headlights working correctly?	Satisfactory		-
Lights: Are the brake lights working correctly?	Satisfactory		-
Lights: Are the turn signals working correctly?	Satisfactory		-
Lights: Are the hazard lights working correctly?	Satisfactory		-
Other: Are the windshield wipers in good condition?	Satisfactory		-
Other: Are the fans and defroster in good condition?	Satisfactory		-
Other: Are the brakes in good condition?	Satisfactory		-
Other: Is the parking brake working correctly?	Satisfactory		-

Other: Are the mirrors in good condition?	Satisfactory	-
Other: Is the horn working correctly?	Satisfactory	-
Other: Is the exhaust system in good condition?	Satisfactory	-
Tires: Are the tires properly inflated?	Satisfactory	-
Tires: Do the tires have adequate tread?	Satisfactory	-
Tires: Is the spare available and properly inflated?	Satisfactory	-
Leaks: Is the vehicle free from oil leaks?	Satisfactory	-
Leaks: Is the vehicle free from all other leaks?	Satisfactory	-
Safety Equipment: Is there a fire extinguisher?	Satisfactory	-
Safety Equipment: Is there a first aid kit?	Satisfactory	-
Safety Equipment: Are there spare bulbs/fuses?	Satisfactory	-
Safety Equipment: Are seat belts in safe condition?	Satisfactory	-
Is the vehicle in acceptable driving condition? If not please describe below	Satisfactory	-