





# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Legacy Construction	<b>Type of Inspection:</b>	Scissor lift
<b>Project</b>	20 126 Smileland Dental	<b>Date of Inspection</b>	April 12, 2021
<b>Inspector Name</b>	Luis Aguilar	<b>Time of Inspection</b>	07:00 AM

## INSPECTION ITEMS

Item		Comment	Photo
Click "Satisfactory" and enter the model # in the comments section below	Satisfactory	genie gr-20	
Is the owners manual in place?	Satisfactory		-
Is the back up alarm or moving alarm working?	Satisfactory		-
Are the guardrails in place?	Satisfactory		-
Are the tires in safe condition?	Satisfactory		-
Is the emergency stop button working?	Satisfactory		-
Are the indicator lights working?	Satisfactory		-
Does the platform extension open and close smoothly and lock into place?	Satisfactory		-
Perform a platform control check. Does everything operate smoothly?	Satisfactory		-
Perform a ground control check. Does everything operate smoothly?	Satisfactory		-
Is the lift in overall good condition and the platform clean?	Satisfactory		-
Are the structure, pins, scissors and covers in good condition?	Satisfactory		-
Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?	Satisfactory		
Does the horn work?	Satisfactory		-