



EQUIPMENT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Legacy Construction	Type of Inspection:	Scissor lift
Project	20 126 Smileland Dental	Date of Inspection	April 19, 2021
Inspector Name	Luis Aguilar	Time of Inspection	07:30 AM

INSPECTION ITEMS

Item		Comment	Photo
Click "Satisfactory" and enter the model # in the comments section below	Satisfactory	GS 1530	-
Is the owners manual in place?	Satisfactory		-
Is the back up alarm or moving alarm working?	Satisfactory		-
Are the guardrails in place?	Satisfactory		-
Are the tires in safe condition?	Satisfactory		-
Is the emergency stop button working?	Satisfactory		-
Are the indicator lights working?	Satisfactory		-
Does the platform extension open and close smoothly and lock into place?	Satisfactory		-
Perform a platform control check. Does everything operate smoothly?	Satisfactory		-
Perform a ground control check. Does everything operate smoothly?	Satisfactory		-
Is the lift in overall good condition and the platform clean?	Satisfactory		-
Are the structure, pins, scissors and covers in good condition?	Satisfactory		-
Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?	Satisfactory		-
Does the horn work?	Satisfactory		-