



# EQUIPMENT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Positive Electric Co.	<b>Type of Inspection:</b>	Boom Lift
<b>Project</b>	Marley Spoon	<b>Date of Inspection</b>	September 22, 2023
<b>Inspector Name</b>	Dominick Santini	<b>Time of Inspection</b>	06:52 AM

## INSPECTION ITEMS

Item		Comment	Photo
Click "Satisfactory" and enter the boom lift model # in the comments below	Satisfactory	600AJ	-
Is the lift in overall good condition and the platform clean?	Satisfactory		-
Are there full body harnesses available with the correct lanyard for those working in the basket?	Satisfactory		-
Are the indicator lights working?	Satisfactory		-
Perform a platform control check. Does everything operate smoothly?	Satisfactory		-
Perform a ground control check. Does everything operate smoothly?	Satisfactory		-
Are the tires in safe condition?	Satisfactory		-
Are the platform anchor point(s) in place and clearly labeled?	Satisfactory		-
Are the guardrails and platform door in securely in place?	Satisfactory		-
Can you clearly see the capacity, weight and limits not the name plate or manufacturer decals?	Satisfactory		-
Is the owners manual in place?	Satisfactory		-
Are the structure, pins and covers in good condition?	Satisfactory		-
Does the horn work?	Satisfactory		-
Is the moving alarm working?	Satisfactory		-