








PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	December 14, 2023
Inspector Name	Connor Gregory	Time of Inspection	01:13 PM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Unsatisfactory	Stored lights	
Was work completed?	Unsatisfactory	Stored lights	
Was work completed?	Unsatisfactory	Lights found stacked	

Was work completed?	Unsatisfactory	Watt stopper devices found in this condition	
Was work completed?	Satisfactory	Existing work. Ups panel	

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
-		
-		
-		