






PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	December 18, 2023
Inspector Name	Connor Gregory	Time of Inspection	02:29 PM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Unsatisfactory	2" pvc in plenum ceiling from IT room to watch room, needs to be replaced	
Was work completed?	Satisfactory	Majority of home runs pulled into and cut into trough above ml6	
Was work completed?	Satisfactory	Both sections of ml6 mounted with feeder pipe completed	
Was work completed?	N/A		-
Was work completed?	N/A		-

UNSATISFACTORY ITEMS

Photo	Comment	Corrective Action
-------	---------	-------------------

