







PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	December 21, 2023
Inspector Name	Connor Gregory	Time of Inspection	08:31 AM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	Roof penetrations	
Was work completed?	Satisfactory	2x2 lights in the ceiling and wired	
Was work completed?	Satisfactory	Sub panel feeder conduits finished	

Was work completed?	Satisfactory	Sub panel feeder conduit supports are now properly secured	
Was work completed?	N/A		-