





PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

| | | | |
|-----------------------|-----------------------|----------------------------|-------------------------|
| Company | Positive Electric Co. | Type of Inspection: | Job Progress Inspection |
| Project | Summit Fire House | Date of Inspection | January 02, 2024 |
| Inspector Name | Connor Gregory | Time of Inspection | 01:48 PM |

INSPECTION ITEMS

| Item | | Comment | Photo |
|---------------------|--------------|---|---|
| Was work completed? | Satisfactory | Hanging light fixtures, running high and low voltage cable for light fixtures on second floor 12/20 |  |
| Was work completed? | Satisfactory | Running rigid conduit thru roof penetrations for roof top units 12/20 |  |
| Was work completed? | N/A | | - |
| Was work completed? | N/A | | - |
| Was work completed? | N/A | | - |