






# PROJECT INSPECTION

Generated by Safety Compliance App [www.safetycompliance.com](http://www.safetycompliance.com) | [www.safetycomplianceapp.com](http://www.safetycomplianceapp.com)

<b>Company</b>	Positive Electric Co.	<b>Type of Inspection:</b>	Job Progress Inspection
<b>Project</b>	Summit Fire House	<b>Date of Inspection</b>	January 02, 2024
<b>Inspector Name</b>	Connor Gregory	<b>Time of Inspection</b>	01:48 PM

## INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	Core drilled hut wall and completed sub panel feeder conduit for panel LS2 12/22	
Was work completed?	Satisfactory	Hanging lights and supporting fixtures and related wiring on second floor 12/22	
Was work completed?	Satisfactory	Hanging lights and supporting related wiring on second floor 12/22	
Was work completed?	N/A		-
Was work completed?	N/A		-