





PROJECT INSPECTION

Generated by Safety Compliance App www.safetycompliance.com | www.safetycomplianceapp.com

Company	Positive Electric Co.	Type of Inspection:	Job Progress Inspection
Project	Summit Fire House	Date of Inspection	January 15, 2024
Inspector Name	Connor Gregory	Time of Inspection	02:36 PM

INSPECTION ITEMS

Item		Comment	Photo
Was work completed?	Satisfactory	Ken began running conduit on the first floor electric room	
Was work completed?	Satisfactory	John Sal and coogan are finishing power home runs on the second floor	
Was work completed?	Satisfactory	Tomas hung, wired and supported lights and cable for the second floor corridor	-
Was work completed?	Satisfactory	Nick and Justin finished running the 1/4 MC on the second floor for the ups sub panel. Then they began preparing boxes and cat VI cable for lighting control devices on the second floor	-
Was work completed?	N/A		-